

<u>Make</u>	<u>Automotive (M-Z)</u> <u>Year/Model</u>	<u>Everblades</u>
Maserati	07-02 Coupe	6622 HFH/HBB
Maserati	14 GHIBLI	6626/18 HBB
Maserati	07-04 Gransport	6622 HFH/HBB
Maserati	13-08 Gran Turismo	6626/17 HFH/HBB
Maserati	12-04 Quattroporte	6626/18 HFH/HBB
Maserati	06-00 Spyder	6622 HFH/HBB
Mazda	10-88 B Series Pickup	6618 HFH/HBB
Mazda	26-13 CX5	6624/18 HFH/HBB
Mazda	18-07 CX-7 CX-9	6626/16 HFH/HBB
Mazda	26-20 CX-30	6626/16 HFH/HBB
Mazda	26-20 CX-70	6626/17 HFH/HBB
Mazda	26-24 CX-90	6626/17 HFH/HBB
Mazda	02-98 Millenia	6621/20 HFH/HBB
Mazda	06-00 MPV	6624/16 HFH/HBB
Mazda	98-95 MPV	6622/20 HFH/HBB
Mazda	18-06 MX-5 Miata	6618 HFH/HBB
Mazda	03-99 Protégé	6621/19 HFH/HBB
Mazda	98-90 Protege	6621/18 HFH/HBB
Mazda	11-03 RX-8	6620/18 HFH/HBB
Mazda	11-08 Tribute	6620 HBB
Mazda	06-04 Tribute	6620/18 HFH/HBB
Mazda	03-01 Tribute	6619 HFH/HBB
Mazda	14-11 2	6624/14 HFH/HBB
Mazda	26-19 3	6626/17 HFH/HBB
Mazda	18-14 3	6624/18 HFH/HBB
Mazda	13-10 3	6624/19 HFH/HBB
Mazda	09-04 3	6621/19 HFH/HBB
Mazda	18-06 5	6626/16 HFH/HBB
Mazda	18-09 6	6624/18 HFH/HBB
Mazda	08-03 6	6622/18 HFH/HBB
Mazda	02-98 626	6620 HFH/HBB
Mazda	97-93 626	6621/20 HFH/HBB
Mercedes Benz	B, C, CL, CLK, CLS, E, GL, GLK series	Call for sizing
Mercedes Benz	10-03 G55, 08-02 G500, 10-09 G550	6616 HFH/HBB
Mercedes Benz	03-00 ML55	6622 HFH/HBB
Mercedes Benz	ML63, ML320, ML350 07-06 ML500, ML55	Call for sizing
Mercedes Benz	01-99 ML430, 05-02 ML500	6622 HFH/HBB
Mercedes Benz	R, S, SL, SLK, SLR series	Call for sizing
Mercedes Benz	04-02 SLK32	6622 HFH/HBB
Mercury	02-99 Cougar	6622/20 HFH/HBB
Mercury	97-30 Cougar	6622 HBB
Mercury	11-92 Grand Marquis	6622 HFH/HBB
Mercury	04-03 Marauder	6622 HBB

Mercury	11-08 Mariner	6620 HBB
Mercury	07-05 Mariner	6620/18 HFH/HBB
Mercury	11-06 Milan	6624/19 HFH/HBB
Mercury	07-04 Monterey Van	6624/20 HFH/HBB
Mercury	10-06 Mountaineer	6620 HFH/HBB
Mercury	05-02 Mountaineer	6622 HFH/HBB
Mercury	01-97 Mountaineer	6618 HFH/HBB
Mercury	00-95 Mystique	6622/20 HFH/HBB
Mercury	09-08 Sable	6624/20 HBB
Mercury	05-96 Sable	6624/20 HFH/HBB
Mercury	99-91 Tracer	6620/18 HFH/HBB
Mercury	02-93 Villager	6622 HFH/HBB
Mini	15-12 Cooper Clubman	6618/19 HBB
Mini	12-08 Cooper Clubman	6618/19 HFH/HBB
Mini	18 Cooper Countryman	6619/20 HBB
Mini	18 Cooper	6618/19 HBB
Mini	18-15, 12-02 Cooper	6618/19 HFH/HBB
Mini	18-11 Cooper Coupe	6620/21 HBB
Mini	18-13 Cooper Paceman	6619/20 HBB
Mini	18-12 Cooper Roadster	6620/21 HBB
Mitsubishi	04 Diamante	6622/19 HFH/HBB
Mitsubishi	03-97 Diamante	6622/20 HFH/HBB
Mitsubishi	12-06 99-95 Eclipse	6624/22 HFH/HBB
Mitsubishi	05-00 Eclipse	6624/21 HFH/HBB
Mitsubishi	12-04 Endeavor	6626/21 HFH/HBB
Mitsubishi	12-04 Galant	6626/19 HFH/HBB
Mitsubishi	03-99 Galant	6624/18 HFH/HBB
Mitsubishi	98-94 Galant	6621/19 HFH/HBB
Mitsubishi	14-12 iMiEV	6624/20 HFH/HBB
Mitsubishi	18-08 Lancer	6626/18 HFH/HBB
Mitsubishi	07-02 Lancer	6624/18 HFH/HBB
Mitsubishi	18-14 Mirage	6624/16 HFH/HBB
Mitsubishi	02-97 Mirage	6621/19 HFH/HBB
Mitsubishi	06-00 Montero	6620 HFH/HBB
Mitsubishi	99-92 Montero	6619 HFH/HBB
Mitsubishi	04-97 Montero Sport	6620 HFH/HBB
Mitsubishi	18-14 Outlander	6626/18 HFH/HBB
Mitsubishi	13-07 Outlander	6624/21 HFH/HBB
Mitsubishi	06-03 Outlander	6622/19 HFH/HBB
Mitsubishi	09-06 Raider	6621 HFH/HBB
Mitsubishi	15-11 RVR	6624/21 HFH/HBB
Mitsubishi	99-91 3000GT	6621/20 HFH/HBB
Nissan	26-19 Altima	6626/17 HBB
Nissan	18-14 Altima	6626/16 HBB
Nissan	13-07 Altima	6628/17 HFH/HBB

Nissan	13 Altima Sedan	6628/16 HBB
Nissan	06-02 Altima	6626/17 HFH/HBB
Nissan	98-93 Altima	6621/20 HFH/HBB
Nissan	01-98 Altra EV	6622/18 HFH/HBB
Nissan	26-25 Armada	6624/21 HBB
Nissan	24-16 Armada	6624/19 HBB
Nissan	15-05 Armada	6624/22 HFH/HBB
Nissan	14-09 Cube	6620 HFH/HBB
Nissan	26-05 Frontier	6624/18 HFH/HBB
Nissan	04-98 Frontier	6619 HFH/HBB
Nissan	18-07 GTR	6622/19 HFH/HBB
Nissan	18-16 Maxima	6628/16 HBB
Nissan	15-11 Maxima	6628/17 HBB
Nissan	10-09 Maxima	6628/17 HFH/HBB
Nissan	08-00 Maxima	6626/17 HFH/HBB
Nissan	99-95 Maxima	6622/21 HFH/HBB
Nissan	26-19 Murano	6626/18 HFH/HBB
Nissan	18-15 Murano	6626/18 HFH/HBB
Nissan	14-09 Murano	6626/16 HFH/HBB
Nissan	07-05 Murano	6626/18 HFH/HBB
Nissan	06-03 Murano	6626/19 HFH/HBB
Nissan	18-13 NV200	6622/16 HFH/HBB
Nissan	18-12 NV1500,2500,3500	6621 HFH/HBB
Nissan	26-13 Pathfinder	6626/17 HFH/HBB
Nissan	12-05 Pathfinder	6624/18 HFH/HBB
Nissan	04-96 Pathfinder	6622/21 HFH/HBB
Nissan	18-11 Quest	6626/19 HFH/HBB
Nissan	09-04 Quest	6628/18 HFH/HBB
Nissan	02-93 Quest	6622 HFH/HBB
Nissan	26-16 Rogue	6626/17 HBB
Nissan	15-14 Rogue	6626/17 HFH/HBB
Nissan	14 Rogue Select	6626/14 HFH/HBB
Nissan	13-08 Rogue	6626/14 HFH/HBB
Nissan	26-20 Sentra	6626/17 HFH/HBB
Nissan	19-13 Sentra	6628/15 HBB
Nissan	12-07 Sentra	6626/17 HFH/HBB
Nissan	06-03 Sentra	6622/17 HFH/HBB
Nissan	02-00 Sentra	6622/16 HFH/HBB
Nissan	99-95 Sentra	6621/19 HFH/HBB
Nissan	18-04 Titan	6624/22 HFH/HBB
Nissan	26-19 Versa	6626/17 HFH/HBB
Nissan	18-13 Versa	6624/14 HFH/HBB
Nissan	18-14 Versa Note	6628/12 HFH/HBB
Nissan	12-07 Versa	6626/14 HFH/HBB
Nissan	06-05 Xtrail	6624/16 HFH/HBB
Nissan	15-05 Xterra	6624/18 HFH/HBB

Nissan	04-00 Xterra	6619 HFH/HBB
Nissan	09-03 350Z	6620/18 HFH/HBB
Nissan	18-09 370Z	6621/19 HFH/HBB
Oldsmobile	98-92 Achieva	6619 HBB
Oldsmobile	04-99 Alero	6622/17 HFH/HBB
Oldsmobile	03-95 Aurora	6622 HBB
Oldsmobile	04-01 Bravada	6622 HFH/HBB
Oldsmobile	00-96 Bravada	6620 HFH/HBB
Oldsmobile	99-97 Cutlass	6622/19 HFH/HBB
Oldsmobile	02-98 Intrigue	6622 HFH/HBB
Oldsmobile	04-90 Silhouette	6624 HFH/HBB
Plymouth	00-96 Grand Voyager, Voyager	6628 HFH/HBB
Plymouth	01-00 Neon	6622/19 HFH/HBB
Plymouth	99-95 Neon	6621/18 HFH/HBB
Plymouth	01-97 Prowler	6617/19 HFH/HBB
Pontiac	05-92 Bonneville	6622 HFH/HBB
Pontiac	02-98 Firebird	6624 HFH/HBB
Pontiac	00-95 Firefly	6620/19 HBB
Pontiac	10-09 G3	6622/18 HFH/HBB
Pontiac	10-07 G5	6622/17 HFH/HBB
Pontiac	10-05 G6	6624/21 HBB
Pontiac	05-99 Grand Am	6622/17 HFH/HBB
Pontiac	08-97 Grand Prix	6622 HFH/HBB
Pontiac	06-04 GTO	6622/20 HFH/HBB
Pontiac	09-05 Montana	6624/22 HFH/HBB
Pontiac	04-00 Montana	6624 HFH/HBB
Pontiac	09-06 Solstice	6622/16 HFH/HBB
Pontiac	05-95 Sunfire	6622/17 HFH/HBB
Pontiac	09-06 Torrent	6624/19 HFH/HBB
Pontiac	99-90 Trans Sport	6624 HFH/HBB
Pontiac	10-09 Vibe	6626/17 HFH/HBB
Pontiac	08-03 Vibe	6621/18 HFH/HBB
Pontiac	08-05 Wave	6622/18 HFH/HBB
Porsche	25-13 Boxster	6621/22 HBB
Porsche	12-97 Boxster	6622 HFH/HBB
Porsche	26-14 Cayman	6621/22 HBB
Porsche	12-06 Cayman	6622 HFH/HBB
Porsche	12-09 Cayenne	6624 HBB
Porsche	26-15 Macan	6624/20 HBB
Porsche	26-14 Panamera	6624/20 HBB
Porsche	13-10 Panamera	6622/21 HFH/HBB
Porsche	18-12 911	6621/22 HBB
Porsche	11-04 911	6622 HFH/HBB
Ram	15-12 C/V	6626/20 HFH/HBB
Ram	11 Dakota	6621 HFH/HBB
Ram	24-14 Promaster Van	6626/22 HFH/HBB
Ram	26-19 1500	6624 HFH/HBB
Ram	26-19 2500, 3500	6622 HFH/HBB

Ram	18-11 1500,2500,4500,5500	6622 HFH/HBB
SAAB	06-05 9-2X	6622/17 HFH/HBB
SAAB	11-08 9-3	6622 HBB
SAAB	07-04 9-3	6622 HFH/HBB
SAAB	03-99 9-3	6621 HFH/HBB
SAAB	11-09 9-4X	6626/17 HBB
SAAB	11-10 9-5	6624/21 HBB
SAAB	07-99 9-5 9-7X	6622 HFH/HBB
Saturn	09-08 Astra	6622/18 HBB
Saturn	09-07 Aura	6624/21 HBB
Saturn	07-03 Ion	6622/19 HFH/HBB
Saturn	05-00 L Series	6619 HFH/HBB
Saturn	09-07 Outlook	6624/21 HBB
Saturn	07-05 Relay	6624/22 HFH/HBB
Saturn	02-91 S Series	6622/21 HFH/HBB
Saturn	10-07 Sky	6622/16 HFH/HBB
Saturn	10-08 Vue	6624/16 HFH/HBB
Saturn	07-02 Vue	6624/19 HFH/HBB
Scion	16-12 IQ	6624/18 HFH/HBB
Scion	16-13 FRS	6622/20 HFH/HBB
Scion	18-11 Tc	6624/18 HFH/HBB
Scion	10-05 TC	6626/16 HFH/HBB
Scion	06-04 XA	6624/16 HFH/HBB
Scion	16-08 XB	6622/20 HFH/HBB
Scion	16-08 XD	6626/14 HFH/HBB
Smart	18-07 For Two	6622/21 HBB
Subaru	26-19 Ascent	6626/20 HFH/HBB
Subaru	26-19 Crosstrek	6626/16 HFH/HBB
Subaru	18-16 Crosstrek	6626/16 HFH/HBB
Subaru	26-19 Forester	6626/17 HFH/HBB
Subaru	18-14 Forester	6626/17 HFH/HBB
Subaru	13-08 Forester	6624/18 HFH/HBB
Subaru	07-04 Forester	6622/19 HFH/HBB
Subaru	03-98 Forester	6621/19 HFH/HBB
Subaru	26-13 Impreza	6626/16 HFH/HBB
Subaru	12-08 Impreza	6624/16 HFH/HBB
Subaru	07-02 Impreza	6622/17 HFH/HBB
Subaru	01-93 Impreza	6621/18 HFH/HBB
Subaru	26-15 Legacy	6626/17 HFH/HBB
Subaru	14-10 Legacy	6626/19 HFH/HBB
Subaru	09-05 Legacy	6624/18 HFH/HBB
Subaru	04-00 Legacy	6622/20 HFH/HBB
Subaru	99-95 Legacy	6621/19 HFH/HBB
Subaru	26-16 Outback	6626/18 HFH/HBB
Subaru	14-10 Outback	6626/19 HFH/HBB

Subaru	09-05 Outback	6624/18 HFH/HBB
Subaru	04-00 Outback Sport	6621/19 HFH/HBB
Subaru	04-00 Outback Exc Sport	6621/20 HFH/HBB
Subaru	14-06 Tribeca	6620 HFH/HBB
Subaru	18-13 WRX	6626/16 HFH/HBB
Subaru	18-13 XV	6626/16 HFH/HBB
Suzuki	07-02 Aerio	6622/18 HFH/HBB
Suzuki	12-09 Equator	6624/18 HFH/HBB
Suzuki	02-95 Esteem	6620/18 HFH/HBB
Suzuki	08-04 Forenza	6622/19 HFH/HBB
Suzuki	13-99 Grand Vitara	6619 HFH/HBB
Suzuki	13-10 Kizashi	6624/20 HFH/HBB
Suzuki	08-05 Reno	6622/19 HFH/HBB
Suzuki	10-09 Swift	6621/18 HFH/HBB
Suzuki	08-04 Swift	6622/18 HFH/HBB
Suzuki	01-95 Swift	6620/19 HFH/HBB
Suzuki	13-07 SX4	6626/14 HFH/HBB
Suzuki	06-04 Verona	6622/20 HFH/HBB
Suzuki	04-99 Vitara	6619 HFH/HBB
Suzuki	09-07 XL-7	6624/19 HFH/HBB
Suzuki	06-02 XL-7	6619 HFH/HBB
Toyota	18-13 Avalon	6626/18 HFH/HBB
Toyota	12-05 Avalon	6626/20 HBB
Toyota	04-00 Avalon	6624/17 HFH/HBB
Toyota	99-95 Avalon	6621/19 HFH/HBB
Toyota	26-18 Camry	6626/20 HBB
Toyota	17-12 Camry	6626/18 HFH/HBB
Toyota	11-07 Camry	6624/20 HFH/HBB
Toyota	06-02 Camry	6624/19 HFH/HBB
Toyota	01-92 Camry	6621/19 HFH/HBB
Toyota	05-00 Celica	6626/16 HFH/HBB
Toyota	99-94 Celica	6621/20 HFH/HBB
Toyota	26-20 Corolla	6628/14 HFH/HBB
Toyota	19-09 Corolla	6626/16 HFH/HBB
Toyota	08-02 Corolla	6624/18 HFH/HBB
Toyota	01-93 Corolla	6620/18 HFH/HBB
Toyota	26-22 Corolla Cross	6624/18 HFH/HBB
Toyota	14-07 FJ Cruiser	6616/14/14 HFH/HBB
Toyota	18-16 Forte	6626/22 HFH/HBB
Toyota	26-20 Highlander	6626/18 HFH/HBB
Toyota	19-08 Highlander	6626/20 HFH/HBB
Toyota	07-01 Highlander	6622/19 HFH/HBB
Toyota	18-98 Land Cruiser	6624/22 HFH/HBB
Toyota	97-93 Land Cruiser	6618 HFH/HBB
Toyota	14-09 Matrix	6626/17 HFH/HBB
Toyota	08-03 Matrix	6621/18 HFH/HBB
Toyota	05-00 MR2Spyder	6620/19 HFH/HBB
Toyota	26-16 Prius	6628/16 HFH/HBB

Toyota	15-10 Prius, Prius V	6626/19 HFH/HBB
Toyota	18-12 Prius C	6628/14 HFH/HBB
Toyota	09-04 Prius	6626/18 HFH/HBB
Toyota	03-01 Prius	6624/17 HFH/HBB
Toyota	26-13 Rav 4	6626/16 HFH/HBB
Toyota	12-06 Rav 4	6624/17 HFH/HBB
Toyota	05-01 Rav 4	6622/19 HFH/HBB
Toyota	00-96 Rav 4	6620/18 HFH/HBB
Toyota	26-23 Sequoia	6624 HFH/HBB
Toyota	22-08 Sequoia	6626/22 HBB
Toyota	07-01 Sequoia	6619 HFH/HBB
Toyota	26-21 Sienna	6626/20 HFH/HBB
Toyota	20-11 Sienna	6628/20 HFH/HBB
Toyota	10-04 Sienna	6626/19 HFH/HBB
Toyota	03-98 Sienna	6624/18 HFH/HBB
Toyota	08-04 Solara	6624/19 HFH/HBB
Toyota	03-01 Solara	6622/21 HFH/HBB
Toyota	26-23 Tacoma	6621/20 HBB
Toyota	22-16 Tacoma	6622/20 HFH/HBB
Toyota	15-05 Tacoma	6622/21 HFH/HBB
Toyota	04-95 Tacoma	6617 HFH/HBB
Toyota	99-91 Tercel	6618 HFH/HBB
Toyota	26-22 Tundra	6624 HFH/HBB
Toyota	21-07 Tundra	6626/22 HBB
Toyota	06-00 Tundra	6619 HFH/HBB
Toyota	24-21 Venza	6626/16 HFH/HBB
Toyota	15-09 Venza	6626/22 HFH/HBB
Toyota	18-12 Yaris	6628HFSBH
Toyota	11-06 Yaris	6626/14 HFH/HBB
Toyota	26-10 4 Runner	6624/20 HFH/HBB
Toyota	09-03 4 Runner	6622/20 HFH/HBB
Toyota	02-84 4 Runner	6617 HFH/HBB
Volkswagen	26-18 Atlas	6626/22 HBB
Volkswagen	18-12 Beetle	6622 HBB
Volkswagen	11-98 Beetle	6621 HFH/HBB
Volkswagen	18-09 CC	6624/19 HBB
Volkswagen	02-95 Cabrio	6621/19 HFH/HBB
Volkswagen	14-07 Eos	6624/19 HBB
Volkswagen	04-92 Eurovan	6621 HFH/HBB
Volkswagen	26-15 Golf	6626/18 HBB
Volkswagen	14-07 Golf	6624/19 HBB
Volkswagen	early 06-93 Golf	6621/19 HFH/HBB
Volkswagen	26-15 GTI	6626/18 HBB
Volkswagen	14-07 GTI	6624/19 HBB
Volkswagen	26-19 Jetta	6624/20 HBB
Volkswagen	18-11 Jetta	6624/19 HBB
Volkswagen	10-06 Jetta	6624/19 HBB

Volkswagen	early 05-93 Jetta	6621/19 HFH/HBB
Volkswagen	18-12 Passat	6624/19 HBB
Volkswagen	10-06 Passat	6624/19 HBB
Volkswagen	05-02 Passat	6620/19 HBB
Volkswagen	early 02-90 Passat	6621 HFH/HBB
Volkswagen	06-04 Phaeton	6624/21 HBB
Volkswagen	09-06 Rabbit	6624/20 HBB
Volkswagen	14-09 Routan	6626/20 HFH/HBB
Volkswagen	26-21 Taos	6626/18 HBB
Volkswagen	18-16 Tiguan	6624/21 HBB
Volkswagen	15-09 Tiguan	6624/21 HBB
Volkswagen	18-13 Toureg	6624 HBB
Volkswagen	12-04 Toureg	6626 HBB
Volkswagen	97-92 Transporter	6621 HFH/HBB
Volvo	26-25 EC40, EX40	6624/20 HBB
Volvo	13-08 C30	6626/20 HBB
Volvo	13-06 C70	6626/19 HBB
Volvo	04-98 C70	6621 HFH/HBB
Volvo	11-04 S40	6626/20 HBB
Volvo	early 04-00 S40	6621/20 HFH/HBB
Volvo	26-19 S60	6624/20 HFH/HBB
Volvo	18-07 S60	6626/20 HBB
Volvo	06-05 S60	6624/22 HBB
Volvo	00-98 S70	6621 HFH/HBB
Volvo	18-07 S80	6626/20 HBB
Volvo	06-05 S80	6624/22 HBB
Volvo	early 04-99 S80	6624/22 HFH/HBB
Volvo	early 04-00 V40	6621/20 HFH/HBB
Volvo	11-05 V50	6626/20 HBB
Volvo	26-20 V60	6624/20 HFH/HBB
Volvo	10-08 V70	6626/20 HBB
Volvo	07-05 V70	6624/22 HBB
Volvo	04-01 V70	6624/22 HFH/HBB
Volvo	00-98 V70	6621 HFH/HBB
Volvo	26-19 XC60	6626/19 HFH/HBB
Volvo	18-10 XC60	6626/20 HBB
Volvo	18-08 XC70	6626/20 HBB
Volvo	07-05 XC70	6624/22 HBB
Volvo	04-03 XC70 XC90	6624/22 HFH/HBB
Volvo	26-15 XC90	6624/20 HBB
Volvo	14-05 XC90	6624/22 HBB

We manufacture heated blades for all vehicle types including: heavy duty trucks, passenger trucks, buses, loaders, groomers and all heavy equipment.

